



Here is a simple way to power WK for standalone applications or when the host PC does not supply a high enough voltage on the serial interface to run WK.